

**DVPro USB 3.1 Host Compatibility List**

Host	Vendor	Model Name	Chip	Connector	Note
USB3.1 Gen2	Lycom	UB-135 <sup>1</sup>	ASM1142	Type C	PCIe powered
USB3.1 Gen2	Lycom	UB-138	ASM1142	Type C+A	PCIe powered
USB3.1 Gen2	Sunix	USB2312	ASM1142	Type A	PCIe powered
USB3.1 Gen2	IOMaster	IOT-U31AC2V3 <sup>2</sup>	ASM1142	Type C	PCIe powered
Thunderbolt 3	Gigabyte	GA-Z170X-UD5 TH	Intel	Type C	Thunderbolt 3
Thunderbolt 3	Dell	XPS 13	Intel	Type C	Thunderbolt 3
Thunderbolt 3	Alienware	13 R2	Intel	Type C	Thunderbolt 3
USB3.1 Gen1	Apple	Macbook(2015)	Intel	Type C	
USB3.1 Gen1	Samsung	ATIV Book 9 Pro	Intel	Type C	USB3.1
Thunderbolt 3	Apple	Macbook Pro 13"(late 2016)	Intel	Type C	Thunderbolt 3

Rev06

## Note:

1. Lycom UB-135/UB-138 will be detected as USB2.0 when E-mark cable is applied.

Please change the cable orientation to solve this

2. Please check with vendor to get the latest version. Shipment before 2016/7 might be problematic in some cases